# STS-117/13A FD 06 Execute Package



MSG	Page(s)	Title
033A	1 - 12	FD06 Flight Plan Revision (pdf)
034	13	FD06 Mission Summary (pdf)
035	14	FD06 Transfer Message (pdf)
037	15	EMU Water Recharge Troubleshooting for Post EVA 2 (pdf)
038	16 - 18	EVA Assessment of OMS Pod Blanket Repair (pdf)
039	19	2B SAW Retract Lighting Information (pdf)
036		FD05 MMT Summary (pdf - Electronic Only)

Approved by FAO: Linda Delapp

Last Updated: Jun 13 2007 11:44AM GMT JEDI (Joint Execute package Development and Integration), v2.04.0003

#### MSG INDEX

MSG NO.	<u>TITLE</u>
033	FD06 Flight Plan

an Revision FD06 Mission Summary FD06 Transfer Message 

FD05 MMT Summary (Electronic Only)

EMU Water Recharge Troubleshooting for Post EVA 2 EVA Assessment of OMS Pod Blanket Repair 

2B SAW Retract Lighting Information

1. In association with the MDM OA2 failure, parameter FC PURGE LN H2 T1 to the SM GPC is lost, which affects Fuel Cell Auto Purge capability. A procedure is being developed to perform future purges via RTCs. In the meantime, fuel cell purges will need to be performed per FUEL CELL PURGE - MANUAL in the ORB OPS, EPS p. 6-7 with the following delta:

 In STEP 1, check with MCC for √PURGE LN H2 T1 > 79 step before continuing in the procedure.

2. While performing the filter inspection, it is not necessary to inspect or clean the filter on the middeck floor air diffuser that is covered with kapton tape.

If you are still having problems with accessing Outlook on the WLES PGSC (STS-7), a reboot may clear up the issue. If you desire, you can perform a reboot of the WLES laptop any time between MET 4/14:10 and 14:30 when there will be no WLES commanding. Following the reboot, perform the following:

### WLES ACTIVATION AND CHECKOUT

(ORB OPS, WLE SENSORS)

Steps 5, 6 only

In step 5 please select 'Primary' for the backup mode.

#### 4. Flight Day 6 Exercise Constraints


The table below summarizes the Shuttle and ISS exercise constraints for today. Except as noted, these constraints are also denoted in your timelines for your reference.


Activity	Exercise Constraints					
	Shuttle	ISS				
P6 2B SAW RETRACT	No exercise during SAW latch or deploy/retract motor or EVA driven operations	No exercise during SAW latch or deploy/retract motor or EVA driven operations				
EVA 2 (during APFR operations from a structure-mounted WIF)	None	No IRED or HC-1 exercise allowed during APFR operations from a structure-mounted WIF (DLA install and some SARJ Launch Lock removals)				
SARJ LAUNCH LOCK AND LAUNCH RESTRAINT REMOVALS*	Unisolated exercise may prevent EVA removal of launch locks and launch restraints	Unisolated exercise may prevent EVA removal of launch locks and launch restraints				


<sup>\*</sup> The exercise constraints for this task are not reflected in your timelines but may be imposed if EV crew has problem with task completion.


#### 5. REPLACE PAGES 2-18, 2-20, AND 3-56 THROUGH 3-63.


FD0	6							06/13/07	06:38:47		REPLANNED
	06/13/07 (164)	12 13		15	16 17			20	21	22	23
β = 46 MET	Day 004	12 13	14	15 16	1,7 	18	19 	20 	21	22	23 005/00
S T S - 1 1 7 7	CDR STURCKOW	SLEEP	PSOL OL SEPMC POST SLEED TEA/G P	W P6 2B P S RETRACT	17   I P I O   N A L F   POST SLEEP   H D L F   B U   T   M	C I F P/T O7 6 T S/U	C RIC E RETRACT	FILTER INSPEC		P/TV SUPPORT	EXERCISE
	PLT/R2/M1 ARCHAMBAULT	SLEEP	POST SLEEP	SSRMS RTRCT VIEWING	POST SLEEP	SSRMS EVA2 MNVR	SSRMS RTRCT EVA	SPRT		SSRMS SPRT	
	MS1/EV3/R1 FORRESTER	SLEEP	POST HYG BE SLEEP PREBREA A/LI	THE CAMPOUT E		EMU C_LK BREATHE DPRS	P SORTIE 2B P6 D EGRESS SAW P & S/U RETRACT	SARJ	ARJ DLA 1 INSTALL	SARJ LOCK	S & RES
	MS2/EV4/M2 SWANSON	SLEEP	POST HYG BE SLEEP PREBREA			EMU C_LK BREATHE DPRS	P SORTIE 2B P6 D EGRESS SAW P & S/U RETRACT S	DPLY SARJ BR	SA	ARJ LOCKS & RES	S
	MS3/EV2/R1 OLIVAS	SLEEP	POST SLEEP	HYG BRK/ HATCH CLS		EMU C_LK BREATHE DPRS	P D P/TV P6 2B SUPPORT RETRACT S	,	V SUPPORT	EXERCISE	P/TV SPRT
	MS4/EV1 REILLY	SLEEP	POST SLEEP	P6 2B RETRACT	POST SLEEP		<u> </u>		EVA 2 (6:30 IVA SPRT As & SARJ		<b>→</b>
D N	FE-2 WILLIAMS	SLEEP	POST SLEEP	HYG BRK/ HATCH CLS		EMU C_LK REATHE DPRS	SSRMS RTRCT EVA	SPRT MI	IDDAY-MEAL BSA		CEVIS
E X P	ISS CDR ЮРЧИХИН	SLEEP	PS 0 0 H POST S	WORK	K   1715	вкд-па	x0-C01-CLS0UT15	C H MIDDAY-M G	IEAL ВКД-ПхО-С	CO1-CLSOUT15	IMS COW
1 5	FE-1 KOTOB	SLEEP	PS - S E 0 0 0 - 8 T E 7 8 8 *	POST DPC S E N W	PREP RED	SSRMS CMO EVA2 OBT MNVR	H/O CWC FILL INIT		MEAL C T W E C R M	XFER	TVIS
U P	FE-2 ANDERSON	SLEEP	POST SLEEP	PREP DPC SODF WARN	<u>A</u>		H/O FILL INIT		C T W E C R	XFER	A D A P 
S T S	SSRMS	72 73	74		75	76	77		78	79	80
	NOTES		*INSTALL *STO	W*HTR ACT . NO .		BIAS -XLV -ZV *MANUAL PU			*TEI		
		F EXERCISE T					NO EXERCISE NO IRED/HC-1				

























## MSG 034 (15-0413) - FD06 MISSION SUMMARY Page 1 of 1 Good Morning Atlantis! The crew continues to do outstanding work. We are ready for another great EVA day. Good luck with EVA 2! YOUR CURRENT ORBIT IS: 184 X 179 NM NOTAMS: MORON (MRN) - CLOSED WAKE ISLAND (WAK) - CLOSED GOOSE BAY (YYR) - RWY 08/26 CLOSED KEFLAVIK (IKF) – UNUSABLE RIO GALLEGOS (AWG) - UNUSABLE **NEXT 2 PLS OPPORTUNITIES:** EDW22 ORB 80 - 4/23:54 (SCT250 230/13P23) EDW22 ORB 95 – 5/22:40 (SKC 230/18P27) OMS TANK FAIL CAPABILITY: L OMS FAIL: NO R OMS FAIL: NO LEAKING OMS PRPLT BURN: L OMS LEAK: ALWAYS RETROGRADE R OMS LEAK: ALWAYS RETROGRADE OMS QUANTITIES(%) L OMS OX = 31.0R OMS OX = 33.0FU = 30.8FU = 32.5SUBTRACT I'CNCT COUNTER FOR CURRENT OMS QUANTITIES **DELTA V AVAILABLE:**

30 31

32 33

34 35

1

2

3

4 5

6 7

8 9

10

11 12

13

14 15 16

17 18

19

20 21

22 23

24 25

26 27

28

29

36 37

38 39

OMS 332 FPS 40 ARCS (TOTAL ABOVE QTY1) 48 FPS 41 TOTAL IN THE AFT 380 FPS

42

43 ARCS (TOTAL ABOVE QTY2) 82 FPS 44 FRCS (ABOVE QTY 1) 25 FPS

45

AFT QTY 1 79 % 46 47 AFT QTY 2 42 %

48 49 50

51 THERE ARE NO FAILURE/IMPACT/WORK AROUNDS FOR TODAY.

## **MSG 035 (15-0414) - FD06 TRANSFER MESSAGE** Page 1 of 9 Good morning crew, You guys are doing great! Today we've added 1 resupply item, 1 return item, and some 5 MLE Bag Layouts to help you pack the bag. The Transfer List Excel file, FD06 TransferList STS117.xls, is located on the KFX machine in C:\OCA-up\transfer. For ISS, the Transfer List Excel file, FD06\_TransferList\_STS117.xls, is located in K:\OCAup\transfer. **Transfer Notes** This message contains bag drawings for 5 MLE Bags A, B, D, and H to help you configure the bags for return. We are still working on the 5 MLE Bag C drawing and will uplink it in a future Transfer message In location MF43C, please stow Return Bag 405 in the back of the locker and Return Bag 401 in the front of the locker (next to the door). This is because bag 405 is heavy and stowing it toward the back will maintain the locker CG needed to protect the locker mounting fasteners. Questions/Answers for the crew None Please incorporate uplink pages as follows: In **LAYOUTS** tab Add Page(s): L-5, L-6, L-8, and L-9 In **RESUPPLY** tab Replace Page(s): 9 In **RETURN** tab Replace Page(s): 2, 6, 8 Changes to the Transfer List are detailed below. RESUPPLY Item 803: New Item

**RETURN** 

42 Item 607: Updated Constraint

Item 703.2, 703.3, 703.4: Added S/N's

Item 804: New Item

Call us with any questions and have a great day!

- The Transfer Team

49 50 51

48

1

2 3

4

5 6

7

8

10

11 12

13

14

15

16 17

18

19

20

21 22

23

2425

26 27

28

29 30

31

32 33

34

35 36 37

38

39

40 41

43

44

## **15-0416 (MSG 037) –** EMU Water Recharge Troubleshooting for Post EVA 2 Page 1 of 1

The Water Recharge performed Post EVA 1 did not pressurize the EMU water tanks as expected. The IRU is suspect, and we need additional data to determine its health. These troubleshooting steps will provide the operating pressure of the IRU pump. The PWR swap is to help rule out this being a PWR issue. The following delta steps should be performed during the 1.506 EMU Water Recharge Post UIA Cap and Plug procedure during Post EVA2: Unstow PWR s/n 1025 and 1023. Use PWR 1025 first. Perform steps 1-18 as written. After step 18, perform the following delta steps: IRU 18.1 H2O Outlet vlv (rotarv) CLOSED 18.2 Monitor IRU Pressure gauge reading stable for ~ 2 minutes 18.3 Report to MCC-H, IRU Pressure and Quantity readings, pressure fluctuations and final constant pressure. If pressure > 10 psi: 18.4 H2O Outlet vIv (rotary) ← EMU SUPPLY. Continue filling EVA2 EMUs per the ISS EMU Water Recharge procedure. If pressure < 10 psi: 18.5 Perform steps 19.1, 19.4 - 19.7 to swap to PWR 1023. 18.6 IRU H2O Outlet vlv (rotary) ← EMU SUPPLY 18.7 sw PUMP  $\rightarrow$  ON 18.8 H2O Outlet vlv (rotary) CLOSED 18.9 Monitor IRU Pressure gage reading stable for ~ 2 minutes 18.10 Report to MCC-H, IRU Pressure and Quantity readings, pressure fluctuations and final constant pressure. 18.11 H2O outlet vlv (rotary) ← EMU SUPPLY 18.12 Pick up at step 20 on MCC-H go 

#### MSG 038 (15-0417) - EVA ASSESSMENT OF OMS POD BLANKET REPAIR Page 1 of 3

The following EVA summary timelines illustrate the two options that are under consideration for the OMS Pod blanket repair.

1) Repair at the beginning of EVA 3 2)


Repair on EVA 4

Both timelines assume the repair technique can be accomplished by a single crewmember working off the SRMS using the PAD, WIF Extender, and APFR. The leading repair technique involves using a surgical stapler to insert staples between the two blankets at two levels (one between the blankets at a buried layer and the other along the surface) with Saffil pins (designed for use with a Tile Overlay repair) staked from the blanket into the adjacent tiles. The secondary method involves stitching one side of the raised blanket to the surrounding blanket (using an IVA EMU Lacing tool, IVA stainless steel thread, and an IVA dental punch tool), and staking with the Saffil pins. The specific task time required for the repair is still under assessment, but it appears feasible to complete the task in the times allotted in either option.

Discussion is still on-going as to which EVA is preferable and we will let you know as soon as a decision is made. As you can imagine, more details are to follow.

#### STS-117 ISS-13A EVA Timelines

(Option 1 - Early EVA 3 OMS Pod Blanket Repair)




Assumptions: 1)Simple repair option requires 1 crew based off SRMS w/ WIF Ext/APFR

Discussion points: 1)If repair is a single person task, want other EV crew to do productive work. The Lab Vent is the highest priority single person task. JR is better trained for this than Danny. Therefore Danny should do repair. 2)Makes sense for SRMS ingress to be somewhere on Lab fwd. 3)Good possibility that 2B could be completely retracted on EVA 3 in which case time for get aheads on EVA 4 increases.

#### **STS-117 ISS-13A EVA Timelines**

(Option 2 - Early EVA 4 OMS Pod Blanket Repair)



This option preserves EVA 1, 2, and 3 as written. Preserves a conservative 2:30 for repair. Free floater tasks during repair are lower priority so it would be lower impact to have him assist throughout repair. This has the least impact on tool logistics during previous EVAs and allows for better repair technique development

## 15-0419 (MSG 039) – 2B SAW Retract Lighting Information Page 1 of 1

The following camera pan/tilt angles can be used to provide additional illumination during 2B SAW retract. These values assume the SSRMS is in the Translate position with the MT at WS3. The SRMS is at the SAW Retract Viewing posn: Outboard 1/3rd of 2B SAW: SSRMS Tip Elbow (+141, +36) SRMS Elbow (+90, -47) Mid 1/3rd of 2B SAW: SSRMS Tip Elbow (+65, +70) SSRMS Base Elbow (-105, -52) (Left Panel only) SRMS Elbow (+80, -40) Inboard 1/3rd of 2B SAW: SSRMS Tip LEE SSRMS Tip Elbow (-3, +45) US LAB: (+150, +29) SRMS Elbow (+65, -25) MBS Mast Camera (-82, -17) (Left Panel only) 

#### MSG 036 (15-0415) - FD05 MMT SUMMARY

Page 1 of 2

#### **FD5 MMT Crew Summary**

The MMT met today to discuss mission progress, the MDM OA2 Card 5 anomaly, debris assessment data, and the Port OMS Pod blanket including EVA repair options. Both the ISS and Shuttle MMT were very pleased with your hard work and outstanding execution of EVA 1 and are enjoying views of the newly deployed solar arrays. There were no significant decisions made during the meeting today.

#### MDM OA2 Card 5:

 The team is assessing impacts for the loss of telemetry on MDM OA2 Card 5 and trying to determine why it failed. There are no mission duration impacts for this failure nor will it adversely affect any of your operations. A power cycle of this MDM will not be pursued at this time because it would also result in a power cycle for the remaining OA MDM's and therefore is not performed for non-critical instrumentation.

#### **Imagery/Debris Assessment Team:**

The TPS for window 5/6 and the Port ET Door tiles were cleared today at the MMT. The final analysis for the protruding gap filler near the arrowhead tile is still being completed since the worst case boundary layer effect envelope a portion of the RCC panels and thus requires more time. Additionally, the team is continuing with final assessments of the Right Inboard Elevon tile that was obscured by shadows and the Aft fuselage gap filler. It is important to note that the team indicates no concern with any of the analysis completed thus far.

The MMT received a summary of the ascent Radar data. All three radars performed very well and tracked the orbiter through ascent. While most of the radar returns are still being understood and correlated with imagery data, one of the returns did correlate with an ET foam loss near the LOX feedline that was noted in the ET feedline camera imagery. There are no concerns with any of the radar data.

There have been two on-orbit Wing Leading Edge Impact Detection Sensor (WLEIDS) indications that the team has noted. The first was noted on the starboard RCC panel 11/12 and the second was on the port RCC 7/8. The team is not concerned because surrounding sensors did not register any response as would be expected with an actual debris impact. This is most likely thermal induced and has been noted on previous missions.

#### **Port OMS Pod Blanket:**

 The team continues to work the details regarding thermal analysis and material testing for the torn blanket and underlying graphite epoxy structure. While no new thermal analysis was provided to the MMT, the team did provide a detailed test plan for Arc Jet and Radiant testing with graphite epoxy panels and for a blanket pull test to assist in development of the EVA repair technique. The blanket pull test will be completed tonight and the Arc Jet and Radiant testing will take longer but results are expected over the next several days.

The MMT was briefed by Team 4 on the different blanket repair options and will decide tomorrow whether the repair will occur on EVA 3 or EVA 4. The operations team has worked hard to keep the repair as simple as possible. These options include using the Saffil pins from the TPS overlay kit, staples from the medical kit stapler, or the EVA servicing kit needle with 22 gauge wire to secure the blanket. Work continues on this and the team fully expects to converge on an agreed to option by tomorrow.

#### MSG 036 (15-0415) - FD05 MMT SUMMARY

Page 2 of 2

- · Cleared damage sites were assessed with Mach 20.6
  - · Remaining work for partial transition due to gap filler & RH inboard Elevon site

